

IMPORTANT!

RPI Part #'s

TUA159, TUA160, TUB161, TUB162, TUD152 & TUD153

The LCD Contrast adjustment and the proper installation of the Microprocessor Chip is crucial to the operation of the PC Boards listed above. It is imperative for proper operation of these PC Boards that the instructions included with the boards are followed in their entirety.

TUD152LBL Rev A (02/21)