




New Parts to fit Midmark • Ritter Tables and Chairs

WARNING: When attaching hydraulic hoses to the cylinders, torque the hose fittings between 55 - 60 Inch Pounds only. Additional torque could damage the threads in the cylinder.


RPI Part #MIH104
OEM Part #002-0004-00

POWER HOSE
Fits: Connects
Motor/Pump to bottom
of Hydraulic Cylinders
Models: 110




RPI Part #MIH106
OEM Part #002-0005-00

RETURN HOSE
Fits: Connects
Motor/Pump to top
of Hydraulic Cylinders
Models: 110




RPI Part #MIH105
OEM Part #002-0109-00

POWER HOSE
Fits: Connects
Motor/Pump to bottom
of Hydraulic Cylinders
Models: 105*




RPI Part #MIH109
OEM Part #002-0110-00

RETURN HOSE
Fits: Connects
Motor/Pump to top
of Hydraulic Cylinders
Models: 105*




RPI Part #MIH108
OEM Part #002-0099-00

POWER HOSE
Fits: Connects
Motor/Pump to
bottom of
Hydraulic
Cylinders
Models: 105* & 305



RPI Part #MIH107
OEM Part #002-0098-00

RETURN HOSE
Fits: Connects
Motor/Pump
to top of
Hydraulic
Cylinders
Models: 105* & 305




RPI Part #MIH100
New OEM Part #002-0144-00
Old OEM Part #002-0054-00

POWER HOSE
Fits: Pump to Base
Models: 106 & 306




RPI Part #MIH101
New OEM Part #002-0143-00
Old OEM Part #002-0053-00

RETURN HOSE
Fits: Pump to Base
Models: 106 & 306




RPI Part #MIH103
OEM Part #002-0096-00

POWER HOSE
Fits: Pump to Base
Models: 107 & 307



RPI Part #MIH102
OEM Part #002-0095-00

RETURN HOSE
Fits: Pump to Base
Models: 107 & 307



* See Chart on Back for Models and Serial Number Breakdowns

For your convenience – Cable Ties also available!

RPI Part #RPT085

CABLE TIE (8" BLACK)
• 25 per package




RPI Part #RPT279

CABLE TIE (8" BLACK)
• 25 per package




RPI Part #RPT375

CABLE TIE (12" BLACK)
• 25 per package



RPI Part #MIC089
OEM Part #002-0094-00


BASE CYLINDER
Fits: Table Base
Models: 105, 107, 305 & 307



Includes Cable Ties

RPI Part #MIC111
OEM Part #002-0100-00


BACK CYLINDER
Fits: Table Back
Models: 105 & 305



Includes Cable Ties

RPI Part #MIC112
OEM Part #002-0137-00


TILT CYLINDER
Fits: Table Base
Models: 112, 113 & 117*



Includes Cable Ties

RPI Part #MIC113
OEM Part #002-0271-00


TILT CYLINDER
Fits: Table Base
Models: 117* & 317



Includes Cable Ties

RPI Part #MIC114
OEM Part #002-0346-00

BACK CYLINDER
Fits: Table Back
Models: 117*, 119*, 311,
317, 318 & 319*



Includes Cable Ties

rpi replacement parts industries, inc.

CALL (800) 221-9723 • FAX (818) 882-7028 • EMAIL order@riparts.com • WEBSITE www.riparts.com

The above parts are manufactured by Replacement Parts Industries, Inc. to fit Midmark•Ritter equipment. All product names used in this document are trademarks or registered trademarks of their respective holders. WEB 07/09

RPI PART #	OEM PART #	DESCRIPTION	MODELS with Prefix and Serial # Breakdown <i>Note: Part fits all prefixes and all serial #'s for models listed if not otherwise noted.</i>
MIC089	002-0094-00	BASE CYLINDER	105-001 thru -006; 107; 305-001 thru -004; 307-001 thru -007
MIC111	002-0100-00	BACK CYLINDER	105-001 thru -006; 305-001 thru -004
MIC112	002-0137-00	TILT CYLINDER	112-001; 113-001; 117-001 thru -003 serial #'s AJ1000 thru AJ3143
MIC113	002-0271-00	TILT CYLINDER	117-001 thru -003 serial #'s AJ3144 & FE1000 thru present; 317-001
MIC114	002-0346-00	BACK CYLINDER	117-001 thru -003 serial #'s FE1000 thru present; 119-001 thru -016 serial #'s BY2006, CA1191, DF2695, EM1000, EN1000, EY1000, EZ1000 & HK1000 thru present; 311-005; 317-001; 318-001; 319-003 thru -006 with prefixes HN, KK, KL & V
MIH100	002-0144-00 002-0054-00	POWER HOSE	106-001 thru -004; 306-001 thru -003
MIH101	002-0143-00 002-0053-00	RETURN HOSE	106-001 thru -004; 306-001 thru -003
MIH102	002-0095-00	RETURN HOSE	107; 307-001 thru -007
MIH103	002-0096-00	POWER HOSE	107; 307-001 thru -007
MIH104	002-0004-00	POWER HOSE	110-001
MIH105	002-0109-00	POWER HOSE	105-001 thru -002 serial #'s G1000 thru G1324 and H1000 thru H1019
MIH106	002-0005-00	RETURN HOSE	110-001
MIH107	002-0098-00	RETURN HOSE	105-001 thru -006 serial #'s G1325, H1020, V1000, CF1000, CG1000 & CA1000 thru present; 305-001 thru -004
MIH108	002-0099-00	POWER HOSE	105-001 thru -006 serial #'s G1325, H1020, V1000, CF1000, CG1000 & CA1000 thru present; 305-001 thru -004
MIH109	002-0110-00	RETURN HOSE	105-001 thru -002 serial #'s G1000 thru G1324 and H1000 thru H1019



replacement parts industries, inc.

P.O. Box 5019 • Chatsworth, California • 91313-5019

PRESORTED STANDARD
U.S. POSTAGE PAID
VAN NUYS, CA
PERMIT #2399

• Address Service Requested •

— An ISO 9001 Certified Company —



rpi Presents New Parts to fit Midmark® Ritter® Tables and Chairs!

For more parts to fit
Midmark® Ritter® Tables and Chairs
including • More Cylinder Kits
• More Return & Power Hose Kits
• Relays • Switches • Hydraulic Fluid
— Go to www.rpiparts.com

